

TROUBLESHOOTING

Possible Error Messages:

'No Transponder Detected' - Displayed when READING

This error message can occur if a transponder key is not properly inserted into the cloning tool reader.

- 1) Make sure transponder key is fully inserted into the cloning tool reader and that you are using the correct cloneable transponder key or chip type.

'No Transponder Detected or Wrong Transponder Type' - Displayed when WRITING

This error message can occur if the wrong transponder key is being used to write on or if the correct transponder key is not properly inserted into the cloning tool reader.

- 1) Make sure transponder key is fully inserted into the cloning tool reader and that you are using the correct cloneable transponder key or chip type.

'Blank TK60'

This message occurs (in Step 3) when Step 2 is not completed correctly.

- 1) Turn the cloning tool off and back on and then start over from Step 1. When performing Step 2, make sure the turning of the ignition procedure is done correctly and in fluid movements.

'Step 2 Wrong'

This message occurs (in Step 3) when Step 2 is not completed correctly.

- 1) Turn the cloning tool off and back on and then start over from Step 1. When performing Step 2, make sure the turning of the ignition procedure is done correctly and in fluid movements.

'Error 03'

This error message occurs when the calculation is unable to find the secret key.

- 1) Turn the cloning tool off and back on and then start over from Step 1.

'Error 62, Try Again'

This error message occurs when the secret key found at the end of the calculation does not match the original key.

- 1) Turn the cloning tool off and back on and then start over from Step 1.

'Error 63, Try Again'

This error message occurs when the ID of the original key at the end of the calculation is different from the one expected.

- 1) Turn the cloning tool off and back on and then start over from Step 1.

'Error XX'

This error message occurs when there is an error in the calculation.

- 1) Turn the cloning tool off and back on and then start over from Step 1.

**For additional information, please visit our website at www.bianchi1770usa.com
or call 800-891-2118 for technical support.**